, , , , , , , , , , , , , , , , , , ,	rmation repor	REPORT NO.	Wa
COUNTRY USSR (Chkalov Chlast)	*	DATE DISTR. 2 AUDIO	י שנגי
SUBJECT Iron Foundry at Chkalo	or contract of the contract of	- 00,00	51.05
25X1C Producing Locomotive F	arts	NO. OF PAGES 1	
	TO OIL	NO. OF ENCLS: 1	
	RETURN TO CIA	O.E.V.	
	LIBRARY	SUPPLEMENT TO REPORT NO.	- ZUA
1. Designation and Location	n of the Difference		T* 25X
residential settlements, length of one side of the	of the town of Chkelov*and A large freight and swit he compound.	tch yard extends the whole	
500 meters. Source knew	of no plans for expanding	m estimated area of 300 x; the plant.	
3. Production: Only cast parties available. Electric	of no plans for expanding arts are made in the plant carts for tenders. Neither power is furnished to the	m estimated area of 300 x; the plant. Such as wheels, frame- a latter shop nor a forge	
3. Production: Only cast partition on a second of the probably employs not more than other Important Installar	of no plans for expanding arts are made in the plant parts for tenders. Neither power is furnished to the le town. The plant operate than 1,000 persons.	m estimated area of 300 x; the plant. s such as wheels, frame- e a latim shop nor a forge plant from an outside s on three shifts and	
3. Production: Only cast partition of the probably employs not more than the probable of the partition	of no plans for expanding arts are made in the plant parts for tenders. Neither power is furnished to the le town. The plant operate than 1,000 persons. tions in the Chkalov Area hop which probably works in dabove. It has both a lang out repair work, pistons	in estimated area of 300 x; the plant. Is such as wheels, frame— Is a lather shop nor a forge plant from an outside Is on three shifts and It is conjunction with the Ithe shop and a stamping Is, piston rods, and driving	
3. Production: Only cast partition only cast partition only cast partition only cast partition of the partition of the probably employs not more than the probably employs not more than the other Important Installar as A locomotive repair slip iron foundry described forge. Besides carrying shafts are produced here. b. A factory for the production of the production of the production in expanding industry.	of no plans for expanding arts are made in the plant parts for tenders. Neither power is furnished to the e town. The plant operate than 1,000 persons. tions in the Chkalov Area hop which probably works id above. It has both a laing out repair work, pistoms ere.	in estimated area of 300 x; the plant. is such as wheels, frame— a latter shop nor a forge plant from an outside s on three shifts and in conjunction with the the shop and a stamping s, piston rods, and driving ich source stated to be	
3. Production: Only cast partitive partis, as well as production: Only cast partitive partis, as well as production: Electric source, probably from the probably employs not more than the probably employs not more than a. A locomotive repair struction foundry described forge. Besides carrying shafts are produced here. A factory for the production of the partition of the par	of no plans for expanding arts are made in the plant parts for tenders. Neither power is furnished to the se town. The plant operate than 1,000 persons. tions in the Chkalov Area hop which probably works in de above. It has both a laining out repair work, pistons ere.	in estimated area of 300 x; the plant. is such as wheels, frame— a lathe shop nor a forge plant from an outside s on three shifts and in conjunction with the the shop and a stamping s, piston rods, and driving ich source stated to be	
3. Production: Only cast partition only cast partition only cast partition only cast partition of the partition of the probably employs not more than the probably employs not more than the company of the company of the product of t	of no plans for expanding arts are made in the plant parts for tenders. Neither power is furnished to the le town. The plant operate than 1,000 persons. The chalev Area hop which probably works in dabove. It has both a laining out repair work, pistons ere. Suction of tank parts, which produces different size there is no automobile in ped to some other place.	in estimated area of 300 x; the plant. The plant is shop nor a forge plant from an outside is on three shifts and In conjunction with the the shop and a stamping ich source stated to be see of radiators for industry in Chkalov.	
3. Production: Only cast partitive partis, as well as production: Only cast partitive partis, as well as production: Electric source, probably from the probably employs not more than the probably employs not more than a. A locomotive repair struction foundry described forge. Besides carrying shafts are produced here. A factory for the production of the partition of the par	of no plans for expanding arts are made in the plant parts for tenders. Neither power is furnished to the le town. The plant operate than 1,000 persons. The chalev Area hop which probably works in dabove. It has both a laining out repair work, pistons ere. Suction of tank parts, which produces different size there is no automobile in ped to some other place.	the plant. The plant. The plant. The plant. The plant from an outside son three shifts and The conjunction with the the shop and a stamping so, piston rods, and driving the source stated to be seed of radiators for in Chkalov.	
3. Production: Only cast partitive parts, as well as prise available. Electric source, probably from the probably employs not more. 4. Other Important Installar as A locomotive repair since forge. Besides carrying shafts are produced here. A factory for the process an expending industry, c. A radiator factory white trucks and cars. Since the radiators are ship.	of no plans for expanding arts are made in the plant parts for tenders. Neither power is furnished to the le town. The plant operate than 1,000 persons. tions in the Chkalov Area hop which probably works is dabove. It has both a lain gout repair work, pistoms ere. duction of tank parts, which produces different size there is no automobile is pped to some other place.	the plant. The plant from an outside son three shifts and The conjunction with the shop and a stamping so, piston rods, and driving the source stated to be seen of radiators for industry in Chkalov. The cument No. 7 Change in Class.	
3. Production: Only cast partitive parts, as well as prise available. Electric source, probably from the probably employs not more. 4. Other Important Installar as A locomotive repair since forge. Besides carrying shafts are produced here. A factory for the process an expending industry, c. A radiator factory white trucks and cars. Since the radiators are ship.	of no plans for expanding arts are made in the plant parts for tenders. Neither power is furnished to the le town. The plant operate than 1,000 persons. Iticas in the Chkalov Area hop which probably works id above. It has both a lain out repair work, pistom ere. Suction of tank parts, which produces different size there is no automobile is pped to some other place.	the plant. The plant. The plant. The plant. The plant. The plant. The plant from an outside son three shifts and The plant from an outside son three shifts and The plant from an outside son three shifts and The plant from an outside son three shifts and The plant from an outside son three shifts and The plant from an outside son three shifts and The plant from an outside son three shifts and stamping son plant from the shifts and driving son plant from the source stated to be seen of radiators for industry in Chalov. The plant.	